

	Type	L#	Hits	Search Text	DBs	Time Stamp	Comments	Error Definition	Errors
1	BRLS	1	3	("6649835" "6419102" "3892049").pn.	USPAT; EPO; JPO	2004/09/23 11:12			0
2	BRLS	2	1	6785981.pn.	USPAT; EPO; JPO	2004/09/23 11:14			0
3	BRLS	3	2	3639998.pn.	USPAT; EPO; JPO	2004/09/23 11:14			0
4	BRLS	4	5	("3381651"   "2941308"   "3286508"   "3398465"   "3409997").PN.	USPAT	2004/09/23 11:18			0
5	BRLS	5	13	3639998.URPN.	USPAT	2004/09/23 11:18			0
6	BRLS	6	20	("2022250"   "2577104"   "3639998"   "3718982"   "3990069"   "4206552"   "4700492"   "4899462"   "5154008"   "5281956"   "5325809"   "5378254"   "5467077"   "5518025"   "5675908"   "5822883"   "6122972"   "6186140"   "6220092"   "6328647").PN.	USPAT	2004/09/23 11:43			0
7	BRLS	7	12	6 and sens\$4	USPAT	2004/09/23 11:44			0
8	BRLS	8	39	6 adn sensor	USPAT	2004/09/23 11:44			0
8	BRLS	8	42	6 adn sensor	USPAT	2004/09/23 11:44			0
9	BRLS	9	10	6 and sensor	USPAT	2004/09/23 12:30			0
10	BRLS	10	60	34/.ccls. and exhaust and drum and (sens\$4 with pressure) and control\$3	USPAT	2004/09/23 13:03			0
11	BRLS	11	8	10 and (alert alarm) and filter	USPAT	2004/09/23 12:45			0

	Type	L #	Hits	Search Text	DBs	Time Stamp	Comments	Error Definition	Errors	
12	BRL S	12	1	3286508.pn.	USPAT	2004/09/23 12:46			0	
13	BRL S	13	17	34/\$.ccls. and exhaust and (sens\$4 with pressure) and control\$3 and filter and (alert alarm)	USPAT	2004/09/23 13:05			0	
14	BRL S	14	4	13 not 8	USPAT	2004/09/23 13:03			0	
15	BRL S	15	9	13 not 11	USPAT	2004/09/23 13:03			0	
16	BRL S	16	44	exhaust and (sens\$4 with pressure) and control\$3 and filter and (alert alarm) and differential	USPAT	2004/09/23 13:05			0	
17	BRL S	17	10	exhaust and (sens\$4 with pressure) and control\$3 and filter and (alert alarm) and differential and airflow	USPAT	2004/09/23 13:06			0	
18	BRL S	18	9	17 and drum	USPAT	2004/09/23 13:06			0	
19	BRL S	19	7	18 not 11 not 13	USPAT	2004/09/23 13:49			0	
20	BRL S	20	1	6792694.pn.	USPAT	2004/09/23 13:50			0	
21	BRL S	21	16	("4081997"   "4275508"   "4286391"   "4397101"   "4531307"   "5291667"   "5443541"   "5444924"   "5570520"   "5673497"   "5755041"   "5764542"   "5822883"   "5860224"   "6158148"   "6637127").PN.	USPAT	2004/09/23 13:50				0

	Type	L #	Hi ts	Search Text	DBs	Time Stamp	Comments	Error Definition	Errors
22	BRL S	22	5	21 and (sens\$4 with pressure)	USPAT	2004/09/23 14:11			0
23	BRL S	23	5	5860224.URPN.	USPAT	2004/09/23 13:59			0
24	BRL S	24	7	21 and (sens\$4 and pressure)	USPAT	2004/09/23 14:12			0
25	BRL S	25	2	24 not 22	USPAT	2004/09/23 14:13			0
26	BRL S	26	3	("5709040""5097606""58602 24").PN.	USPAT	2004/09/23 14:53			0
27	BRL S	27	2	("3639998" "6785981").pn.	USPAT	2004/09/23 14:53			0

	Document ID	Issue Date	Title	Current OR	Current XRef	Inventor
1	US 6637127 B2	2003 1028	Dryer airflow sensor	34/527	34/140; 34/546; 34/572; 34/606	Reede, Ivan et al.
2	US 6158148 A	2000 1212	Method for detecting impermissible operating states in a hot-air clothes dryer, and a dryer with such a detection method	34/497	34/499; 34/549	Krausch, Uwe-Jens
3	US 5860224 A	1999 0119	Testing for blocked dryer vent	34/418	34/606; 34/607	Larson, Eric K.
4	US 5822883 A	1998 1020	Exhaust air particulate contamination sensing for tumbler dryers	34/494	34/495	Horwitz, Steven A.
5	US 5764542 A	1998 0609	Noise filtering utilizing running average	702/179	709/202	Gaudette, Marvin F. et al.
6	US 5755041 A	1998 0526	Infrared temperature sensing for tumble drying control	34/491	34/495; 34/497	Horwitz, Steven A.
7	US 5673497 A	1997 1007	Clothes dryer temperature control system	34/486	34/491; 34/549; 34/553; 34/562	St. Louis, Robert
8	US 5570520 A	1996 1105	Clothes dryer dryness detection system	34/535	34/491; 34/557	Huffington, Jeffrey M.
9	US 5444924 A	1995 0829	Electronic control of clothes dryer	34/486	34/562	Joslin, Dan F. et al.
10	US 5443541 A	1995 0822	Dual element electrical clother dryer with single element interrupt circuit	34/486	34/491; 34/549; 34/553; 34/562	St. Louis, Robert M.
11	US 5291667 A	1994 0308	Electronic control of clothes dryer	34/526	34/535; 34/550; 34/89	Joslin, Dan F. et al.
12	US 4531307 A	1985 0730	Fabric dryer control with cycle interrupt	34/552	D32/5	Kuecker, Pamela M.
13	US 4397101 A	1983 0809	Automatic dryer control	34/486	34/495; 34/562	Rickard, Jimmy R.
14	US 4286391 A	1981 0901	Control system for an automatic clothes dryer	34/543		Gerry, Otto F.

	<b>Document ID</b>	<b>Issue Date</b>	<b>Title</b>	<b>Current OR</b>	<b>Current XRef</b>	<b>Inventor</b>
15	US 4275508 A	1981 0630	Clothes dryer temperature control system	34/524	116/216; 338/22R; 34/63; 340/595	Jones, William H.
16	US 4081997 A	1978 0404	Clothes dryer air flow test device and method	73/168		Losert, Gerhard K.